



**SPARES for ROYAL ENFIELD & AMAL**

**HITCHCOCK'S MOTORCYCLES LTD  
OLDWICH LANE WEST  
CHADWICK END  
SOLIHULL  
B93 OEY                      ENGLAND**

**E-MAIL [info@hitchcocksmotorcycles.com](mailto:info@hitchcocksmotorcycles.com)**

**WEB [www.hitchcocksmotorcycles.com](http://www.hitchcocksmotorcycles.com)**

**TELEPHONE: 01564 783 192**

**FAX: 01564 783 313**

**PART NUMBERS: 90128 / 90128A FLYWHEEL SET.**

Please note when assembling the above crank/flywheel the existing crank thrust washers located either side of the conrod are not required to be fitted.

The reason for this is that our flywheels are hardened and ground thus eliminating the need for thrust washers.

If in any doubt when assembling the flywheels always consult a qualified engineer.